


# Table of Contents

<b>How to post-process the printed parts</b> .....	3
Step 1 - Why to post-process the printed parts? .....	4
Step 2 - Tools used for the post-processing .....	5
Step 3 - Optional tools for post-processing .....	6
Step 4 - Printed parts for post-processing .....	7
Step 5 - General post processing (tips and tricks) .....	8
Step 6 - General post processing (tips and tricks) .....	8
Step 7 - Y-axis parts post-processing .....	9
Step 8 - X-axis parts post-processing .....	9
Step 9 - X-axis parts post-processing .....	10
Step 10 - E-axis parts post-processing .....	10
Step 11 - E-axis parts post-processing .....	11
Step 12 - E-axis parts post-processing .....	11
Step 13 - E-axis parts post-processing .....	12
Step 14 - LCD parts post-processing .....	13



# How to post-process the printed parts



[help.prusa3d.com/g18680](https://help.prusa3d.com/g18680)

Scan the QR code to  
display the latest  
version of this  
chapter.





## STEP 1 Why to post-process the printed parts?




- ◆ This guide will explain in detail, **how to post-process printed parts** used on Original Prusa i3 printers **to ensure easy assembly afterwards**.
- ◆ **Some printed parts** designed for Original Prusa printers **require post-processing**. Skipping this part might cause issues and damage to the parts during the assembly.
- ◆ 3D printing is a very accurate manufacturing process, but there are some factors, which can affect the final printed part:
  - ◆ **Temporary supports** - must be removed after the print
  - ◆ **Different material properties** - not all PETG or ABS are equal
  - ◆ **Defects in prints** - strings, imperfections due to the geometry

## STEP 2 Tools used for the post-processing



 **WARNING:** following tools can easily harm you. Make sure you read the manual from the tool manufacturer!

 **ALWAYS** use protective equipment like safety glasses and gloves.

### ● Recommended tools for this manual:

- **Sharp and thin cutting blade**, the best option is a scalpel, but utility knife is also possible to use.
- **Twist drill bits, ideally with a flat head**, but those aren't easy to find. The lower the angle on the bit's head the better. For printed parts you need two sizes:
  - 8.1 mm / 0.3-inch drill bit (or slightly bigger, but not smaller)
  - 3 mm / 0.12-inch drill bit (or slightly bigger, but not smaller)
- **Pliers with thin/slim jaw are the best**, you can also use the bundled ones, but you might not be able to reach certain places.

## STEP 3 Optional tools for post-processing




- ◆ Following tools are not needed, though if you want to achieve the perfect shape and look we advise to use them:
  - ◆ **Curved/rounded scalpel** - some parts of the printed part are easier to clean with a curved blade.
  - ◆ **Heat gun** - certain materials tend to create strings during the print. Easiest way to remove them is by using a flow of hot air.
- ⓘ Optimal temperature for the heat gun is 250 °C (482 °F) and blow on the parts from a distance of 10 - 15cm (4 - 6 inches).
- ⚠ **WARNING: Blowing hot air from a shorter distance can damage even melt the part!**
- ⚠ **Do not touch the HOT PARTS of the heat gun!!!**

## STEP 4 Printed parts for post-processing




- After the print is finished, all parts should be checked for visible defects. Basic tips are given in:
  - General post processing (tips and tricks)
- Some printed parts require specific post-processing, use the steps listed below:
  - Y-axis parts post-processing
  - X-axis parts post-processing
  - E-axis parts post-processing
  - LCD parts post-processing

## STEP 5 General post processing (tips and tricks)




- Use pliers to carefully remove the temporary supports.
- Clean the screw and rod holes using drill bits. Avoid increasing the diameter of the hole.
- Use a scalpel or utility knife and carefully remove the "elephant foot" (squished first layer) from the edges of the printed parts.

## STEP 6 General post processing (tips and tricks)



- Use the heat gun to remove the strings on each printed parts.
- i** Set the heat gun temperature to 250 °C (482 °F)
- Blow the printed part from a distance of 10 - 15 cm (4 inch - 6 inch) until the strings melt.
- i** Some strings may be thicker and may not simply melt. Remove them with the scalpel.
- !** **WARNING: Blowing hot air from a shorter distance can damage the part.**


## STEP 7 Y-axis parts post-processing



**(i) NOTE:** This step is for the **MK3S** only

- Use a scalpel to remove debris in the screw groove on the Y-belt tensioner.
- Use a 3 mm (0.12 inch) drill bit to clean all screw holes on the Y-axis plastic parts.


## STEP 8 X-axis parts post-processing



- Clean the holes by drill bit 8.1 mm (0.3 inch) in the X-end-motor and the X-end-idler marked in the picture for easier insertion of the rods.
- The drill bit must be parallel to the hole axis.**
- Check the drill tip position through the square hole. **Do not drill the bottom of the hole!**
- Insert the rod into each cleaned hole. Try to slightly pull in and pull out the rod. **The rod must not move freely in the printed part.**
- Use a 3 mm (0.12 inch) drill bit to clean all screw holes on the X-axis plastic parts.

---


## STEP 9 X-axis parts post-processing



- Cut the groove on the top surface of the X-end-motor and the X-end-idler for easier insertion of bearings into the holes.

---

## STEP 10 E-axis parts post-processing



- Use pliers to remove the print support on the fan-shroud.

## STEP 11 E-axis parts post-processing



- 🔷 Cut the groove on the P.I.N.D.A. sensor holder with a scalpel on the extruder-body.
- ⬛ Use a 3 mm (0.12 inch) drill bit to clean all screw holes on the E-axis plastic parts.

## STEP 12 E-axis parts post-processing



- 🔷 Drill both holes on the extruder-idler with a 3 mm (0.12 inch) drill bit.
- ⚠️ **It is CRUCIAL to drill both holes at the same time!**
- ⬛ In the most cases, the printed fs-lever part requires removal of the edge of the first layer. This edge may subsequently cause **malfunction of the filament sensor**.
- 🟠 Carefully remove the edge with a scalpel, focus on the corner shown in the picture.

## STEP 13 E-axis parts post-processing



**(i) NOTE:** This step is for **MK3S/MK2.5S** and you will need the steel ball.

- Insert a piece of filament through the adapter-printer part to clean both filament guiding holes.
- Insert the steel ball and roll with the ball to all sides to ensure smooth movement.
- Push a piece of filament through the hole multiple times to clean it on the fs-cover part. **Do not use 3mm (0.12inch) drill bit for cleaning this hole!**
- Use the 3mm (0.12inch) drill bit for cleaning the screw hole.

**⚠ NOTE: The filament guiding holes must be properly cleaned!**

## STEP 14 LCD parts post-processing



- ◆ Use pliers and carefully remove the temporary supports in the SD card slot on LCD-cover.
- ◆ Remove both temporary supports on the longer side, but keep the inclined part above, which will "lock" the PCB of the LCD in place (see the picture).



---

---

---

---

---

---

---

---

---

---



---

---

---

---

---

---

---

---

---

---



---

---

---

---

---

---

---

---

---

---

